




**Tool for fixing of EPS rotor Part No. TLS20073**



| <b>Alternative part number</b> | <b>Application</b>   |
|--------------------------------|--|
| HLL00323                       | LAND ROVER RANGE ROVER 2012-<br>LAND ROVER RANGE ROVER SPORT 2013-<br>LINCOLN CONTINENTAL 2016-<br>FORD FUSION II 2012-<br>LINCOLN MKZ I 2006-2012 |

More new products at <https://www.atg-components.com/warehouse-news>