



Adjustment screw BMW LAND ROVER Part No. HLR00095



Application
d1 - 17.2 d2 - 37.6 D - 40.5 h1 - 7.5 H - 12.5 M41x1.5 BMW 5/6/7 SERIES ZF

FITS THE FOLLOWING

Rack part number	Crossreferences	Application
ATGE40391RB	BMW 32105A01C20, 32106869208, 32106791190, 32106791984, 32106795190, 32106795234, 32106798386, 32106798398, 32106799215, 32106799935, 32106850042, 32106850625, 32106852276, 32106854143, 32106856426, 32106858131, 32106858135, 32106860174, 32106864844, 32106864846, 32106865433, 32106867958, 32106867960, 32106867961, 32106868347, 32106869208, 32106869210, 32106870788, 32106873500, 32106883539, 32106883543, 32106883546, 32109850042, 32104066221 Bosch KS01000771, KS00000801, 7806974359, KS01003984, KS00002832, KS00000787, KS00000795, KS00000801, KS01000771, KS01000757, KS01000765	BMW 5 Series VI (F10/F11/F07) (2009-2013) 6 Series III (F06/F13/F12) (2011-2017) 7 Series V (F01/F02/F04) (2008-2012) 7 Series V (F01/F02/F04) Restyling (2012-2015)
ATGR20031RB	BMW 32135A0A0B5, 32136761823, 32136769267, 32136751283, 6769267, 6751283, 32136761822, 32136751153, 6763343,	BMW X5 I (E53) (1999-2006)



	32136769268, 32136760114, 6769268, 32106769268, 6761822	
ATGR20121RB	LAND ROVER QEB000130, QEB000052, QEB500480, QEB000150, QEB000053, QEB000051, QEB500402, QEB000130E, QEB000052E, QEB500580, LR005942, QEB00052E	Land Rover Range Rover III (2002-2012)
ATGR20221RB	BMW 32105A4BCE0, 32136772016, 32106777452, 32136767888, 32136776912, 32106780124, 32106780122	BMW 5 Series V (E6x) (2002-2010)
ATGR20251RB	BMW 6761823, 32136751027, 6751027, 32106763342, 32136761823	BMW X5 I (E53) (1999-2006)
ATGR21801RB	BMW 32136755872, 32106768750, 32106761055, 32136764720, 32106779579, 32106768118, 32106755872, 32136761055, 32106777271, 32106764720, 32136768750	BMW 7 Series IV (E6x) (2001-2008)

More new products at <https://www.atg-components.com/warehouse-news>