



Ball screw nut repair kit Ford Part No. 24610189



Application
Ford Explorer 2010-2015

FITS THE FOLLOWING

Rack part number	Crossreferences	Application
ATGE41151RB	FORD BB5Z3504BE, BB533504FA, BB533504BA, BB5Z3504FE, BB5Z3504AE, BB533504EA, BB5Z3504HE, BB5Z3504EE, BB533504FB, BB533504CA, BB5Z3504G INA A00229, A0022905, F565922, H095231142, F56592202, H0952311421, 452001957, 16H0403, F565922, F565922020061, F565922020061CC	Ford Explorer V (2010-2015)
ATGE40431RB	FORD BB5Z3504DE, DB533D080BB, BB533504GB, BB5Z3504NE, DB5Z3504D, BB533504CB,	Ford Explorer V (2010-2015)



	BB5Z3504H, DB533D080BD, BB5Z3504D, BB5Z3504SE, BB533504GA, BB5Z3504LE, DB533D080BF, BB5Z3504GE, DB533D080BC, BB5Z3504CE, BB5Z3504RE, DB5Z3504DE, BB533504DA, BB5Z3504JE, DB533D080BE INA A00229, A0022905, F565922, H095231142, F56592202, H0952311421, 452001957, 16H0403, F565922, F565922020061, F565922020061CC	
--	--	--

More new products at <https://www.atg-components.com/warehouse-news>