



**Steering rack repair kit Part No. 24540244**



<b>Application</b>
Mercedes-Benz Sprinter (901, 902, 903, 904) 1995-2006; Volkswagen LT (901, 902, 903, 904) 1996-2006; Pinion bottom 25*34*7

**FITS THE FOLLOWING**

<b>Rack part number</b>	<b>Crossreferences</b>	<b>Application</b>
ATGR20891RB	Bosch  KS01000011  MERCEDES  9014600190, 901460320080, A9014600800, A901460410080, 901460270080, 9014604500, A9014602900, 9014601500, 901460410080, A9014601900, A9014604500, 9014603200, A9014600190, A9014604100, 9014602700, 901460430080, A901460270080, A9044600200, 9014600800, 9014604100, A9014601500, A9014604300, 9014602900, 9014605100, A9014603200,	Mercedes-Benz  901, 902, 903, 904 (1995 - 2006)  Volkswagen  2DX (1996 - 2006)



	<p>9014601900, 9014604300, A9014602700, A9014605100</p> <p>VAG</p> <p>2D1422055EX, 2D1422055A, 2D1422055GX, 2D1422055E, 2D1422055, 2D1422055G, 2D1422055C</p>	
--	---	--

More new products at <https://www.atg-components.com/warehouse-news>