



**Steering rack repair kit Part No. 25540476**



| Application   |
|---|
| (LITE) FORD Fiesta/Fusion 2001-, MAZDA 2 2003 Visteon |

**FITS THE FOLLOWING**

| Rack part number | Crossreferences  | Application   |
|------------------|--|---|
| ATGR23001RB      | <p>ATG</p> <p>ATGR23001RB, ATGR23002RB, ATGR23001NW, ATGR23002NW</p> <p>FORD</p> <p>1336677, 1418619, 2S613200KF, 2S613200PC, 4386252, VR256C3550, 1352973, 1760698, 2S613200MD, 4356872, 4472936, 1347869, 1465900, 2S613200KR, 2S6C3200KP, 4397223, 1360874, 2N113200CA, 2S613200PB, 4374700, RM2S6J3503KN, 1351610,</p> | <p>Ford</p> <p>Fiesta V (2001-2009)</p> <p>Fusion I (2002-2012)</p> <p>Mazda 2 I (DY) (2003-2007)</p> |



|  |   |  |
|--|---|--|
|  | <p>1631754, 2S613200MC, 4344071,<br/>4452244, 1336686, 1418654,<br/>2S613200KP, 2S6C3200KN,<br/>4387041, 1352976, 2N113200AF,<br/>2S613200PA, 4358909, 4472938,<br/>RF2S6C3550KD, 1351310,<br/>1474309, 2S613200MA,<br/>4329684, 4452242</p> <p>GENERAL RICAMBI</p> <p>FO9041, FO9040</p> <p>MAZDA</p> <p>DE9032960E, DE9032960B,<br/>DE9032960G, DE9032960D,<br/>DE9032960A, DE9032960F,<br/>DE9032960C, DE9032960,<br/>DE9032960H</p> |  |
|--|---|--|

More new products at <https://www.atg-components.com/warehouse-news>