



**Tool for rack bar rod guide Part No. TLS20072**



| <b>Application</b>   |
|--|
| Lincoln Continental 2016-; Ford Fusion II 2012-; Lincoln MKZ I 2006-2012; Mercedes-Benz E-Class (W212, S212) 2009-; Mercedes-Benz CLS-Class II (W218) 2011- (4MATIC) |

**FITS THE FOLLOWING**

| <b>Rack part number</b> | <b>Crossreferences</b>  | <b>Application</b>   |
|-------------------------|---|--|
| ATGE45161RB             | Ford<br><br>7819974121, G3GC3D070DE,<br>7838974872, G3GC3D070AN,<br>7838974874, G3GC3D070EG   | Lincoln<br>Continental X (2016-2020)   |
| ATGE40881RB             | FORD<br><br>DG9C3D080AH,<br>EG9Z3504A, DG9Z3504BE,<br>HG9C3D080AK,<br>DG9C3D080AK, FG9Z3504B,<br>EG9C3D080AC,<br>DG9Z3504AE,<br>HG9C3D080AJ,<br>DG9C3D080AJ,<br>EG9Z3504AE, DG9Z3504CE, | Ford<br>Fusion II (2013-)<br><br>Lincoln<br>MKZ I (Zephyr) (2009-2012)<br>MKZ II (2012-2016) |



|             |  |  |
|-------------|--|--|
|             | HG9Z3504AE,<br>DG9C3D080AL,<br>FG9Z3504CE  |  |
| ATGE40661RB | Bosch<br><br>KS00001957, KS01001789,<br>KS00001953, KS01001785<br><br>MERCEDES<br><br>A2124604500, 2124609000,<br>A2124606300, 2124606300,<br>A2124605500, A2124609800,<br>2124605200, 2124609900,<br>A2124607700, 2124607700,<br>A2124606200, 2124606200,<br>A2124605200, A2124609000,<br>2124604500, 2124609800,<br>A2124607100, 2124607100,<br>A2124605600, A2124609900,<br>2124605600, A2124604500,<br>A2124608400 | Mercedes-Benz<br>CLS-Class II (W218) (2011-2017)<br>E-Class (W212, S212, C207) (2013-2016) |

More new products at <https://www.atg-components.com/warehouse-news>