



**Torque sensor cable Part No. 40270032**



Application
BMW 1 F20, 1 F21, BMW 3 F30, 3 F31, 3 F35 2011-

**FITS THE FOLLOWING**

Rack part number	Crossreferences	Application
ATGE40701RB	BMW 32106854894, 32106863856, 32106874852, 32106858782, 32106874418, 32106891184, 32106857150, 32106864769, 32106883663, 32106862370, 32106874850, 32106892965, 32106858538, 32106868827, 32106884404, 32106856588, 32106864247, 32106883264, 32106859253, 32106874839, 32106891186, CSB75303GS,	BMW 1er II (F20-F21) (2011 - 2017) 3er VI (F3x) (2012 - 2017)



	32106858011, 32106868237, 32106884402 Bosch KS00000794, KS00003355, KS01004097, KS00001961, KS01000764	
ATGE40741RB	MOTORHERZ E40741RB, E40742RB BMW 32106859309, 32106874106, 32106868920, 32106864291, 32106886306, 32106872351, 32106867855, 32106889122, 32106862300, 32106881371, 32106870469, 32106864975, 32106886308	BMW 1er II (F20-F21) (2011 - 2017) 2 Series (F22) (2014 - 2017) 3er VI (F3x) (2012 - 2017) 4er (2013 - )
ATGE41111RB	BMW 32106854887, 32106863466, 32106870455, 32106877774, 32106859296 , 32106867845, 32106874674, 32106886292, 32106857283, 32106864158, 32106872370, 32106881031, 32106862287, 32106868880, 32106875231, 32106859248, 32106864961, 32106872790, 32106886290, 32106856461, 32106863714, 32106871127, 32106881029, 32106861507, 32106868878, 32106874676, 32106889106, 32106859218, 32106864268, 32106872372, 32106881264	BMW 1er II (F20-F21) (2011 - 2017) 2 Series (F22) (2014 - 2017) 3er VI (F3x) (2012 - 2017) 4er (2013 - )
ATGE41821RB	BMW 32106881067, 32106874108, 32106881072, 32106877790, 32106870474, 32106881069, 32106875209, 32106870472, 32106881276	BMW 1er II (F20-F21) (2011 - 2017) 2 Series (F22) (2014 - 2017) 3er VI (F3x) (2012 - 2017) 4er (2013 - )
ATGE42121RB	BMW 32108053268, 32108092391, 32107854808, 32108073860, 32107852660	BMW 3er VI (F3x) (2012 - 2017) 4er (2013 - )



More new products at <https://www.atg-components.com/warehouse-news>