



Tool for dismantling of rotor double row bearing Part No. TLS20124



| Application |
|--|
| AUDI A4 2011-2015; AUDI A4 ALLROAD 2012-2015; AUDI A5 2011-2015 (2,9); AUDI Q5 2012-2017; AUDI A6 2011-2018; AUDI A7 SPORTBACK 2010-2018 |

FITS THE FOLLOWING

| Rack part number | Crossreferences | Application |
|------------------|---|---|
| ATGE40571RB | ATG ATGE40571RB, ATGE40572RB, ATGE40571NMU, ATGE40572NMU SK KJ1SK45, H12171355, J03270741, H09101433, J04292300, A67934, A6793411011, 1310990510, 131099051010, 1520711877, 152071187711 VAG 8K1423055AC, 8K1423055S, 8K1423055BK, 8K1423055AN, 8K1423055CA, 8K1423055BF, 8K1423055AJ, 8K1423055BR, 8K1423055AS | Audi A4 IV (B8) Restyling (2011-2015) A4 allroad IV (B8) Restyling (2009- 2016) A5 I Restyling (2011-2016) |



| | | |
|-------------|--|--|
| ATGE40591RB | VAG 8R1423055E, 8R1423055AS, 8R1423055E, 8R1423055T, 8R1423055AC, 8R1423055BA, 8R1423055L, 8R1423055AF, 8R1423055BE, 8R1423055R, 8R1423055J, 8R1423055AJ, 8R1423055BG | Audi Q5 I Restyling (2012-2017) |
| ATGE40141RB | ATG ATGE40142NMU, ATGE40141NMU, ATGE40142RB, ATGE40141RB, ATGE40142NW, ATGE40141NW INA INADE61, F10280517, A23142110, A2314211011, 1000154420, 100015442011, 1610212918, 161021291811 MOTORHERZ E40142RB, E40141RB VAG 4G1423055EA, 4G1423055DK, 4G1423055BQ, 4G1423055BQ, 4G1423055AK, 4G0909144J, 4G1423055DC, 4G1423055BA, 4G1423055AH, 4G1423105D, 4G0909144G, 4G1423055CS, 4G1423055AN, 4G1423055AA, 4G1423055Q | Audi A6 IV (C7) (2011-2018) A7 I (2010-2014) |

More new products at <https://www.atg-components.com/warehouse-news>