




Torque sensor cable Part No. 40270060



Application
FORD Explorer 2012-2015 with automated parking system (2.75 turn) FORD Explorer 2012-2015 less automated parking system FORD Focus III 2011-, FORD Tourneo Connect II 2013- FORD Kuga I 2013-2016 FORD Transit/Conect CHC 2014-

FITS THE FOLLOWING

Rack part number	Crossreferences	Application
ATGE41161RB	FORD DB5Z3504BE, EB5Z3504J, DB5Z3504LE, EB5Z3504E, DB5Z3504D, EB5Z3504ME, EB5Z3504B	Ford Explorer V (2010 - 2015)
ATGE43621RB	FORD	Ford Explorer V (2010 - 2015)



	DB533D080AF, DB5Z3504E, EB5Z3504G, DB5Z3504AE, DB5Z3504NE, DB533D08AC, DB5Z3504FE, EB5Z3504LE, DB5Z3504CE, EB5Z3504D, DB533D08AE, DB5Z3504KE, DB533D08AB, DB5Z3504F, EB5Z3504H, DB5Z3504C, EB5Z3504A, DB533D08AD, DB5Z3504HE	
ATGE40331RB	FORD 1732061, 1890473, 1869081, 1855327, 2037177, 1880730, 1868628, BV6C3D070, 1754788, 1900377, 1870373, 1861246	Ford Focus III (2011 - 2018) Tourneo Connect II (2013 -)
ATGE41321RB	FORD 2383667, 1818965, 1939536, CV6C3D070LF, CV6C3D070LR, 1869081, CV6C3D070LC, CV6C3D070LL, 1830265, 2027027, CV6C3D070LH, 1900377, CV6C3D070LE, CV6C3D070LP, 1861246, 2113758, CV6C3D070LK, 1823699, 2008952, CV6C3D070LG, CV6C3D070LS, 1880730, CV6C3D070LD, CV6C3D070LM, 1842146, 2052546, CV6C3D070LJ	Ford Kuga II (2012 - 2016)
ATGE41471RB	FORD CV6Z3504A, CV6Z3504ZJ, CV6Z3504E, CV6Z3504UE, CV6Z3504B, CV6Z3504ZJA, CV6Z3504L	Ford Transit Connect II (2012-2018)

More new products at <https://www.atg-components.com/warehouse-news>